UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,907,818 B2 APPLICATION NO. : 10/695965

95965

DATED INVENTOR(S)

: June 21, 2005 : Maurice Anderson

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 8, lines 19-20:

"(SP)-[(P_{108})×(A_2)]>(P_{112})×(A_1)" should read -- (SP)-[(P_{108})×(A_2)]>-(P_{112})×(A_1) --.

Col. 12, lines 43-45, Claim 26.

"F-[a pressure in the service chamber $(P_{108})]\times(A_2)$ >[a pressure in the spring cavity $(P_{112})]\times(A_1)$ " should read — F-[a pressure in the service chamber $(P_{108})]\times(A_2)$ >-[a pressure in the spring cavity $(P_{112})]\times(A_1)$ --.

Signed and Sealed this

Page 1 of 1

Twenty-sixth Day of February, 2008

JON W. DUDAS
Director of the United States Patent and Trademark Office